



Compass Software

KEYBOARD SHORTCUTS COMPASS SOFTWARE



QUICK OVERVIEW

Keyboard shortcuts Compass Software

General

ALT	Make keyboard shortcuts visible
ALT + F4	Close program
CTRL + A	Select all
CTRL + C	Copy
CTRL + V	Paste
CTRL + S	Save
CTRL + Z	Undo
CTRL + Y	Redo
CTRL + O	Open
CTRL + X	Cut
CTRL + P	Print
CTRL + L	Change language
CTRL + U	Activate/deactivate fractions
F1	Help
F6	Switch windows during split-frame
ESC	Close window
DEL	Delete

Tree Menu

+	Expand tree
-	Collapse tree

Window View

+	Zoom in
-	Zoom out
HOME	Zoom over all
END	To the bottom/right end of drawing

Keyboard shortcuts Compass Software

Measuring/ Snap Functions

#	Measure distance
<	Measure angle
CTRL + 1	Snap to Endpoints
CTRL + 2	Snap to Midpoints
CTRL + 3	Snap Projection
CTRL + 4	Snap to Intersection
CTRL + 5	Snap to tangent
0	No grid
1	0.001 mm grid
2	0.005 mm grid
3	0.01 mm grid
4	0.05 mm grid
5	0.1 mm grid
6	0.5 mm grid
7	1 mm grid
8	5 mm grid
9, 10	Grid measurements automatically convert to centimeter
CTRL + #	Switch tooltip with coordinates

Construction

CTRL + SHIFT + ALT	Immediate BGL Save Mode on/off
CTRL + ALT + Q	Export work area information (for internal purposes)
CTRL + Left Mouse Key + Layer	Shows only the layer you clicked on
CTRL + H	Display/hide help lines
CTRL + F	Display/hide photos imported with Flexijet
CTRL + O	Display/hide In-Situ Concrete Core
<i>Correction of Winding:</i>	
G	Set straight
L	Calculate run on walking-line (going-line)
H	Divide harmonically
U	Divide equally
Z	Change measurements
<i>Baluster:</i>	
Z	Divide equally

Keyboard shortcuts Compass Software

Free-form Construction

Drawing arc + Page Up/Page Down	While drawing an arc, will adjust starting angle
Drawing line/arc/line2points + SHIFT	while drawing free-form arc, line, or arc with 2 points, endpoint will snap to vertical or horizontal axis
Continue line/arc + Right Mouse Key	Toggle between straight and curved line
CTRL + I	Import
CTRL + E	Export
CTRL + D	Move point (mouse)
CTRL + D	Move (dialogue)
CTRL + Left Mouse Key	Move (mouse)
CTRL + Arrow Keys	Move selected element (line, arc, circle etc.)
F	Continue line (mouse)
SHIFT + F	Continue line (dialogue)
F + A	Continue arc (mouse)
U	Disconnect (dialogue)
SHIFT + E	Ellipse (dialogue)
SHIFT + N	Polygon with N edges (dialogue)
SHIFT + S	Scale (dialogue)
SHIFT + P	Parallel lines (dialogue)
L	Line with 2 endpoints (mouse)
SHIFT + L	Line with 2 points (dialogue)
A	Arc with 2 points (mouse)
SHIFT + A	Arc with 3 points (mouse)
C	Draw circle from center point (mouse)
SHIFT + C	Circle (dialogue)
I	New point (mouse)
SHIFT + I	New point (dialogue)
M	Modify
DEL	Delete all marked elements
SHIFT + DEL	Delete all unmarked elements
Space	Automatically extend (selected element)
Back Space	Reduce intersection points (selected element)

Keyboard shortcuts Compass Software

Forms

F5	Recalculate
Page Up	Next page
Page Down	Previous page

Vacuum cups (View)

SHIFT + Left Mouse Key	Turn clamping device
------------------------	----------------------